

Corner I.D. # 113T

MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 28, Township 10N, Range 1E,**Monument Description & Remarks:** 2-1/2" Aluminum Monument, 30" long, set 0.1' below grade.


(This monument is not a PLSS corner. It was set as part of a Geodetic Control Survey.)

Recovery Tie Drawing

9/1/2016, Rachel Savich Oser, Fbk. 48, pg. 8

9/4/2018, Cassidy Raley, Fbk. 52, pg. 33


Monument recovered in good condition. Flush with grade.



I, Matthew L. Cooper, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 9th day of June, 2004 A.D.

Indiana Registered Land Surveyor No. LS20200079





0 50 100 200
Feet



Image Source: 2014 Monroe County Pictometry

Office of the Monroe County Surveyor
2004 Geodetic Control Project
119 West 7th Street
Bloomington, Indiana 47404
(812) 349-2570

